

Award Bios Setup (2C4I9R01)

	TYPE	SIZE	CYLS	HEAD	PRECOMP	LANDZ	SECTOR	MODE
Drive C :	User	Mb			0			Normal
Drive D :	None	0Mb	0	0	0	0	0	-----
Drive A	:	None						
Drive B	:	1.44M, 3.5 in.						
Video	:	EGA / VGA						
Halt On	:	All Errors						

BIOS FEATURES SETUP

Virus Warning	:	Disabled	Video BIOS Shadow	:	Enabled
CPU Internal Cache	:	Enabled	C8000-CFFFF Shadow	:	Disabled
External Cache	:	Enabled	D0000-D7FFF Shadow	:	Disabled
Quick Power On Self Test	:	Enabled	D8000-DFFFF Shadow	:	Disabled
Boot Sequence	:	C, A	E0000-E7FFF Shadow	:	Disabled
Swap Floppy Drive	:	Disabled	E8000-EFFFF Shadow	:	Disabled
Boot Up Floppy Seek	:	Disabled			
Boot Up NumLock Status	:	On			
IDE HDD Block Mode	:	Disabled			
Typematic Rate Setting	:	Disabled			
Typematic Rate (Chars/Sec)	:	6			
Typematic Delay (Msec)	:	250			
Security Option	:	Setup			

CHIPSET FEATURES SETUP

Auto Configuration	:	Disable
AT Bus Clock	:	1/4 CLKIN
DRAM Speed	:	Slowest
Cache Burst Read	:	2T
Cache Write Cycle	:	3T
DRAM Write Burst	:	Disabled
Hidden Refresh	:	Enabled
External Cache WB/WT	:	WB
System Shadow	:	Cacheable
Video Shadow	:	Cacheable

POWER MANAGEMENT

Power Management	:	Disabled
ALL OTHERS	:	Disregard