

Award Bios Setup (2A4L6D4C)

HARD DISKS	TYPE	SIZE	CYLS	HEAD	PRECOMP	LANDZ	SECTOR	MODE
Primary Master	: Auto	0	0	0	0	0	0	Auto
Primary Slave	: None	0	0	0	0	0	0	-----
Secondary Master	: None	0	0	0	0	0	0	-----
Secondary Slave	: None	0	0	0	0	0	0	-----

Drive A : None
Drive B : 1.44M, 3.5 in.

Video : EGA/VGA
Halt On : All Errors

BIOS FEATURES SETUP

Virus Warning	: Disabled	Video BIOS Shadow	: Enabled
CPU Internal Cache	: Enabled	C8000-CBFFF Shadow	: Disabled
External Cache	: Enabled	CC000-CFFFF shadow	: Disabled
		D0000-D3FFF Shadow	: Disabled
Quick Power On Self Test	: Enabled	D4000-D7FFF Shadow	: Disabled
Boot Sequence	: C, A	D8000-DBFFF Shadow	: Disabled
Swap Floppy Drive	: Disabled	DC000-DFFFF Shadow	: Disabled
Boot up Floppy Drive	: Disabled		
Boot up NumLock Status	: On		
Boot up System Speed	: High		
Gate A20 Option	: Normal		
Memory Parity Check	: Disabled		
Typematic Rate Setting	: Disabled		
Typematic Rate (Chars/Sec)	: 6		
Typematic Rate (Msec)	: 250		
Security Option	: Setup		
IDE Second Channel Control	: Disabled		
PCI/VGA Palette Snoop	: Enabled		

CHIPSET FEATURES SETUP

Decoupled Refresh	: Enabled	Onboard Local Bus	: Enabled
Video BIOS Cacheable	: Enabled	IDE HDD Block Mode	: Enabled
System BIOS Cacheable	: Enabled	IDE Primary Master PIO	: Auto
External Cache Scheme	: Write Back	IDE Primary Slave PIO	: Auto
Combine Alter & Tag Bits	: Disabled	Secondary IDE Controller	: Disabled
CHRDY for ISA Master	: Enabled	Onboard FDC Controller	: Enabled
Memory Hole At 15Mb Addr.	: Disabled	Onboard Serial Port 1	: COM1/3F8
Cache Timing Control	: Normal	Onboard Serial Port 2	: Disabled
DRAM Timing Control	: Normal	Onboard Parallel Port	: 378/IRQ7
Fast DRAM	: Enabled	Onboard Parallel Mode	: SPP
Burst Write	: Disabled		
CPU Write Back Cache	: Disabled		
Set Turbo pin function	: Suspend		
Set Mouse Lock	: Disabled		

PNP/PCI Configuration

PnP BIOS Auto Config	: Enabled	CPU to PCI Write Buffer	: Disabled
PCI Slot Using INT#	: Auto	PCI Master Write Buffer	: Disabled
PCI IRQ Activated By:	: Level	PCI Master Prefetch	: Disabled
PCI IDE IRQ Map To	: ISA	PCI Master Burst Read	: Disabled
		PCI Dynamic Decoding	: Disabled
		FRAME Generation	: Normal
		Local Memory Detect Point	: Slow
		PCI Burst	: Disabled
		C2P Fast Back-to-Back	: Disabled
		PCI Master 1 WS Write	: Disabled